

## TEST REPORT

Page 1 of 3

**REPORT NUMBER :** TURT200113467  
**APPLICANT NAME :** Balonevi Sanayi ve Ticaret A.Ş.  
**ADDRESS :** Tuzla Deri Organize Bölgesi 9.Yol. B 8 ParselTuzla İstanbul / TURKEY  
TEL:0216 394 00 65 FAX:0216 394 00 66  
**Attention :** Tuğçe Ünlü ( tugce.unlu@balonevi.com )  
**BUYER :** TOYS  
**SAMPLE DESCRIPTION :** One sample of Orange baloon  
**DATE IN :** 3 September ,2020 ( 13:12:00 )  
**DATE OUT :** 10 September ,2020  
**REFERENCE/STYLE NO :** BBP12050-16BBP12100-16,BBM10100-16,BBP12101-16,BBPS260050-16,BBP12025-16,BBP10103-16,BBP10102-16  
**FIBER COMPOSITION :** Not Given  
**PROVIDED CARE LABEL :** Not Given

	SAMPLE
TEST	1
Solvent Migration	P

P = MEETS BUYER' S REQUIREMENT / F = DOES NOT MEET BUYER' S REQUIREMENT / NR = NO REQUIREMENT / SC=STILL CONTINUES / X=NOT PERFORMED / NA = NOT APPLICABLE / LS = LACK OF SAMPLE / NC = NO COMMENT / I = INCONCLUSIVE / # = SEE RESULT / NF = NEEDS FURTHER TESTING / A = ABSENT / M = MARGINAL ACCEPT / SD = SEE DETAILS ENCLOSED / FS: FURTHER STEPS

This report (including any enclosures and attachments) are prepared for the exclusive use of the Customer(s) named in the report and solely for the purpose for which it is provided and on the basis of instructions and information and/or materials supplied by Intertek's Customer. The test results relate only to the specific items tested and are not intended to be a recommendation for any particular course of action. Customer is responsible for acting as it sees fit on the basis of such results. Unless Intertek provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party, nor could it be used for PR activities. Intertek do not accept any liability if this report is used for an alternative purpose from which it is intended, nor do Intertek owe any duty of care to any third party in respect of this report. Except where explicitly agreed in writing, all work and services performed is governed by Intertek Standard Terms and Conditions of Service which is available on request or can be obtained at <http://www.intertek.com/terms>. Testing reports without signature are not valid. The sample has been provided by the customer and the results apply to the sample as received. Sample information is supplied by the customer. Unless otherwise requested, this laboratory applies shared risk decision rule.

Aşkın GÜNERİ  
Customer Care Executive

Zeynep AKIN  
Chemical Laboratory Manager

**Intertek Test Hizmetleri A.S.**  
Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL  
Phone : +90 212 496 46 46 Fax: +90 212 452 80 55  
e-mail : [intertekcg.turkiye@intertek.com](mailto:intertekcg.turkiye@intertek.com)  
<http://www.intertek-turkey.com>



200113467

## RESULTS

REPORT :TURT200113467

Page 2 of 3

10 September ,2020

TOYS

Test Method	Results	Requirements	
<b>Solvent Migration</b>			
EN 71 Part 10 and 11 : 2005			
	<b>RESULT</b>	<b>REPORTING LIMIT</b>	
Trichloroethylene	Not Detected	0.005 mg/L	0.02 mg/L
Dichloromethane	Not Detected	0.02 mg/L	0.06 mg/L
Methanol	Not Detected	1.5 mg/L	5 mg/L
Nitrobenzene	Not Detected	0.005 mg/L	0.02 mg/L
Cyclohexanone	Not Detected	15 mg/L	46 mg/L
3,5,5-Trimethyl-2-Cyclohexane-1- -One	Not Detected	1 mg/L	3 mg/L
Toluene	Not Detected	0.5 mg/L	2 mg/L
Ethylbenzene	Not Detected	0.3 mg/L	1 mg/L
Xylene (All Isomers)	Not Detected	0.5 mg/L	2 mg/L
2-Methoxyethyl Acetate	Not Detected	0.1 mg/L	0.5 mg/L
2-Ethoxyethanol	Not Detected	0.1 mg/L	0.5 mg/L
2-Ethoxyethyl Acetate	Not Detected	0.1 mg/L	0.5 mg/L
Bis (2-Methoxyethyl) Ether	Not Detected	0.1 mg/L	0.5 mg/L
2-Methoxypropyl Acetate	Not Detected	0.1 mg/L	0.5 mg/L

**Intertek Test Hizmetleri A.S.***Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL**Phone : +90 212 496 46 46 Fax: +90 212 452 80 55**e-mail : [intertekcg.turkiye@intertek.com](mailto:intertekcg.turkiye@intertek.com)**<http://www.intertek-turkey.com>*



---

## END OF TEST REPORT ##